

51. Condition of Property

- Excellent Ruin
 Good/Fair Destroyed/Burned
 Deteriorated Date _____

54. Farmstead Plan



52. Historic Outbuildings and Dependencies

Barn Type(s)

- Corn Crib or Shed Summer Kitchen Silo
 Smoke House Spring House Ice House
 Designed Landscape Features Privy Garage

53. Affiliated OAI Site Number(s) _____

OAI Completed? _____

Archaeological Feature:	Observed	Expected on Basis of Archival Research
Well	_____	_____
Privy	_____	_____
Cistern	_____	_____
Foundation	_____	_____
Structural Rubble	_____	_____
Formal Trash Dump	_____	_____
Other _____	_____	_____

42. Further Description of Important Interior and Exterior Features (Continued from page 1)

with a large keystone. The north side of the church has a row of larger windows that follow this same form, and the south side of the church is covered by an addition that fits fairly well with the rest of the building but destroys its symmetry. Almost all of the windows have a smooth stone slip sill, and the corners of the building have quoins executed in brick. At the front peak of the roof there is a large wooden cupola, which is decorated with quoins, a dentilled entablature, an elaborate balustrade, a round-arched vent on each side, a decorated frieze, and a convexly-curved pyramidal roof with a finial spike on top.

43. History and Significance (Continued from page 1.)

on July 7, 1927, and dedicated the building the next year (Lermond, Carlson). In 1968, they built an addition on the south side of the building (Auditor). Today, Dr. O. French Ball is the pastor of First Methodist, and the congregation allows other community members to use its building for various purposes, including a rock band composed of college students who rehearse in one of the rooms at the back of the building.